

**Client No.** \_\_\_\_\_ **Report No.** LTADS130924/0026  
**Item No.** 41031


*The Lifting Operations and Lifting Equipment Regulations 1998 Regulation 9(3) (LOLER)  
The Lifting Operations and Lifting Equipment Regulations (North Ireland )1999, 1998 Regulation 9(2)(3) (LOLER)  
The Safety, Health & Welfare at Work (General Application) Regulations 2007  
The Provision and Use of Work Equipment Regulations 1998 (PUWER)*

Client	Client Site
Anglia Door Systems Ltd Thetford House Roman Way Thetford IP24 1XB	Anglia Door Systems Ltd Thetford house Roman Way Thetford IP24 1XB
<b>Detailed Location</b>	Warehouse

*Note: if this is the first examination, then the report must be retained in accordance with Regulation 11 (2) of LOLER and Regulation 30 of the safety, Health and welfare at work Regulation as applicable*

<b>A)</b>	<b>This examination has been carried out under LOLER periodic examination.</b>	
<b>B)</b>	<b>Were examinations in accordance with an examination scheme?</b>	No

**Item description** LIFTING - Crane - Block Manual - <= 5 ton  
**Make**  
**Model/Type**  
**Serial Number** 21108011  
**Plant Number** AD3  
**Year of Manufacture** 2013  
  
**SWL** 1 tonne



<b>A) Defects found which give rise to imminent danger that requires immediate attention.</b>
None
<b>B) Defects found that could in time give rise to danger and require attention within a specified time.</b>
None

**Client No.**

**Report No.**

LTADS130924/0026

**Item No.**

41031


**Additional remarks and defects.**

--	--	--	--	--

<p><b>Observations and General Comments:</b></p> <p>Slight wear to chain links - suitable for further service. Recommend periodic servicing. No other apparent</p>
--

I certify that on the date stated I thoroughly examined this item of plant and that, subject to any remedial action(s) to defects noted on this report, which are or could become a danger to persons, the item is safe to operate. This declaration is made on the understanding that the equipment will be correctly and suitably maintained.

<p>LiftTech Inspection Services Ltd 10a Castle Meadow Norwich Norfolk United Kingdom NR1 3DE mark@liftechinspection.com 07873 547276</p>
--

<b>Date of examination</b>	13/09/2024
<b>Date of last examination</b>	Unknown
<b>Date of next examination</b>	13/09/2025
<b>E/S print name</b>	Mark Jones
<b>Signature</b>	
<b>Qualification</b>	EngTech MIMechE